



Figure 3d (FER-229) - Detail of vicinity of Pepperdine University and Winter Mesa: faults mapped by consultants for site specific projects. Locality numbers from Figure 3c.

Faults west of Pepperdine (west of Marie Canyon) from Converse Consultants (1981). Faults on Pepperdine campus and in Marie Canyon were observed during grading for sewage treatment ponds and tennis courts (Leighton & Assoc., 1980; Converse Consultants, 1981; Slosson and Associates, various office files; notes of CDMG geologists). Faults east of Malibu Canyon Road from Leighton & Assoc. (1989). Faults south of Pacific Coast Highway (PCH) from Converse Consultants (1986) and Yerkes and Campbell (1980). Malibu Bowl fault does not appear to be as continuous as suggested by more regional mapping (see Figure 3c).